

# Parts Tree

Every painter needs some way to paint doors and fenders. The parts tree has 6 hooks to support 2 doors or 2 fenders at a time. Paint both the inside and out, both at the same time. No more wires hanging your parts, allowing them to move around while you chase them with the paint gun. No more dropping doors after they're painted. This stand is heavy duty. You can even do prep work on it. It has a sturdy 30" x 36" base with 3" casters. Roll it into the paint booth and start painting.



W-C3SP3023



AT-PT-ASSY

Made of heavy 1.5" and 2.0" square tubing so its nice and sturdy.

30"x 36" base. 5 feet tall.

Four 3" casters with ball bearing on the axle.

It has 6 hooks, 3 on each side, so you can hang 2 doors on it at the same time.

It also has 4 smaller pins on it to hook fenders.

Paint 2 doors, 2 fenders or a door and a fender, front and back.